



December 11, 2012

Re: Renovate Education Space – Phase 3, Building #4
VA Project Number: 636a6-10-209
BBSAE Project №: 07063.04

RESPONSE TO BIDDER'S QUESTIONS:

1. The casement window is wider than it is tall and they saw a number of problems with the double hung and casement combination. I will not be able to provide this type of window and will be providing an alternate to use a flush stacked window system with a fixed window above a casement window. .

Revise all new windows shown on drawing to be double hung windows.

Wayne Smith, AIA, CSI, CCS
Architect Specifier

Cc: File